



## Technical Service Bulletin

---

Reference:

**TSB10-GEN-021**

Date:

**Sept 2010**

**APPLIED VEHICLE: All Vehicles**

**SERVICE INFORMATION:**

**Low or Spongy Pedal after caliper replacement, all vehicles**

**Make sure calipers are installed on the correct sides of the vehicle with bleeder valves towards the top of the caliper. The caliper cannot be bled of air if the bleeder is on the bottom.**